

SPILL REPORT

BCAO
RENTON DIVISION

DATE: 12-10-90

BY: Dan McKay

LOCATION OF SPILL: Stall B-4

DATE OF SPILL: 12-10-90 TIME OF SPILL: 19:55

SPILL REPORTED BY: Tom Thorning ORGAN: R-3450 PHONE: 655-1041 655-1721 AT 01:50 AM PM

MATERIAL SPILLED: Jet Fuel ESTIMATED QUANTITY: 5 gallon

CONTAINED ON SITE: ☒ SPILLED TO DRAIN: ☐ SPILLED TO SURFACE WATER: ☐

REGULATORY AGENCIES NOTIFIED: YES ☐ NO ☒ TIME: _____ NOTIFIED BY: _____

WHICH AGENCIES AND PERSONS:

BOEING OFFICES NOTIFIED:

DIRECTOR OF FACILITIES ☐
ENVIRONMENTAL AFFAIRS ☐

PUBLIC AFFAIRS ☐
PUBLIC RELATIONS ☐

CAUSE OF SPILL: Spill came from vent during fueling of airplane

RESPONSIBILITY FOR SPILL: _____ FINE: _____

ACTIONS TAKEN AND BY WHOM: Airplane mechanics cleaned up spill.

FOLLOW-UP ACTION REQUIRED: _____

DISTRIBUTION:

R. A. ATKINS	4-1720	26-77
W.R. DIEFENDERFER	R-6520	63-32
D. A. PETERS	R-6001	93-03
J. A. WALTERS	R-6402	27-43

REVISED 5-13-85

B-DUW2-2457683